



70002

# ABC 1.0 BRIEF MANUAL


TOP  
BOARD



DON'T SCREW  
ME TOO TIGHT!



Before connecting anything, make sure that your system is disconnected from power and the polarity of the ribbon cable is correct!



BILL  
OF MATERIALS

- 4 x 100k resistor
- 9 x 10k resistor
- 2 x 1k resistor
- 4 x 100nF capacitors
- 10 x 10uF capacitors
- 2 x 1N4007 diode
- 8 x jack connector
- 1 x TL74
- 2 x PCB
- 6 x 100k logarithmic potentiometer
- 2 x 100mA fuse
- 1 x 14pin DIL socket
- 1 x 2x11 male pinheader
- 1 x 2x3 female pinheader
- 1 x ribbon cable 2x8
- 3 x jumpers
- 1 x 11mm nut - nut spacer
- 1 x 10mm nut - screw spacer
- 8 x jack washers
- 8 x jack nuts
- 2 x 6mm screws
- 2 x 8mm screws
- 1 x front panel